

**ASBESTOS & REGULATED WASTE  
ASSESSMENT REPORT**

**BRIDGE# 5034  
LYONS TOWNSHIP  
LYON COUNTY, MN**



**Prepared for:**

**Lyon County Highway Department  
Suhail Kanwar, P.E., County Engineer**

**September 22, 2011**

**TABLE OF CONTENTS**

	<b>Page</b>
<b>Site Specifics &amp; Certifications</b>	<b>3</b>
<b>Summary of all Asbestos &amp; Regulated Waste &amp; Actions Required for this Demolition</b>	<b>4</b>
<b>2.1 Asbestos Summary</b>	<b>4</b>
<b>2.2 Lead Summary</b>	<b>4</b>
<b>2.3 Regulated Waste Summary</b>	<b>4</b>
<b>Appendix I Sample location Photographs</b>	<b>5-7</b>
<b>Appendix II Site Location Photographs</b>	<b>8-11</b>
<b>Appendix III MN/DOT Structure Inventory Report</b>	<b>12-15</b>
<b>Appendix IV Laboratory Analysis Report</b>	<b>16</b>
<b>Appendix V Chain of Custody Documents</b>	<b>17-18</b>
<b>Appendix VI Laboratory Accreditations</b>	<b>19-20</b>
<b>Appendix VII Inspectors Licensure and Certification</b>	<b>21</b>
<b>Appendix VIII MPCA Notification of Intent to Perform a Bridge Demolition for MN/DOT Operations Form</b>	<b>22</b>
<b>Appendix IX Notification Form on Transfer of Bridge Steel</b>	<b>23</b>
<b>Appendix X Notification Form on Ownership Transfer of Treated Wood</b>	<b>24-25</b>

**Site Specifics & Certifications**

**Bridge No.:** 5034

**Location:** On CR 83 over Redwood River, 2.1 Mi. Southwest of Jct. CSAH 5, in Lyons Township, Lyon County, Minnesota; Sec 05, T110N, R42W.

**Type of Structure:** Bridge # 5034 is a 75.0' x 28.0', single span, steel Warren low truss bridge built in 1931.

**Railing:** Steel angle iron affixed to truss members.

**Decking:** P-I-C concrete.

**Superstructure:** P-I-C concrete deck with monolithic concrete surface with no membrane present per MN/DOT Structure Inventory Report dated 05/10/2011, and site inspection 06/15/2011.

**Substructure:** P-I-C concrete on steel pile bent each abutment. See MN/DOT Structure Inventory Report dated 05/10/2011 and Site Photographs Appendix II.


**Current Owner:** Lyon County.

**Disposition of Structure:** Demolition

**Licensure:** MDH Certified Asbestos Inspector, Ernest G. Fiala, P.E. Conducted this Inspection (See Appendix IV).

**Certification:** The undersigned certifies that this asbestos inspection was performed on June 15, 2011, in compliance with MN Rules 4620.3460.

**This report was compiled under my direct supervision. I have reviewed the report's contents and find it to meet MN/DOT requirements as described in the "Asbestos & Regulated Waste Manual for Structure Demolition or Relocations for Construction Projects."**



**Ernest G. Fiala, P.E. Reg. No. 18480  
MDH Asbestos Inspector #AI10135**

## **Summary of all Asbestos & Regulated Waste & Actions Required for this Demolition**

**Based on a field inspection, the following conclusions are summarized for Asbestos & Regulated Waste Assessment. Applicable items listed below should be removed and/or stabilized prior to demolition of Bridge # 5034.**

### **2.1 Asbestos Summary**

**No asbestos or asbestos containing materials were found on structure.**

### **2.2 Lead Summary**

**Sample LP-I was taken from the abutment girder near the pin connection at the SW corner of bridge and indicated a lead presence of 44%.**

**Sample LP-2 was taken from the stringer beam near the rocker pin connection at the NE corner of bridge and indicated a lead presence of 38%.**

**Sample LP-3 was taken from the truss member, downstream side of bridge at midspan and indicated a lead presence of 42%.**

**Sample LP-4 was taken from the gusset plate at the SW corner of bridge and indicated a lead presence of 42%.**

**Sample LP-5 was taken the gusset plate at the NE corner of bridge and indicated a lead presence of 42%.**

**Sample LP-6 was taken from the top member of truss structure, South side of bridge at midspan and indicated a lead presence of 39%.**

**Pictures of all sample locations are included in Appendix I.**

### **2.3 Regulated Waste Summary**

**The following Regulated Waste was observed on or in the vicinity of the bridge.**

**2.3.1 Mercury – None**

**2.3.2 PCBs – None**

**2.3.3 CFCs – None**


**2.3.4 Treated wood –None**

**2.3.5 Household Hazardous Waste - None.**


**2.3.6 White Goods - None.**

**2.3.7 Solid Waste - None.**

**Appendix I**  
**Sample Location Photographs**




**Sample LP-1. Lead paint sample from abutment girder, SW corner of bridge.**



**Sample LP-2. Lead paint sample from stringer beam at NE corner of bridge.**



**Sample LP-3. Lead paint sample from truss member.  
Downstream side of bridge at midspan.**



**Sample LP-4. Lead paint sample from gusset plate at SW corner of bridge.**




**Sample LP-5. Lead paint sample from gusset plate at NE corner of bridge.**



**Sample LP-6. Lead paint sample from top truss member, South side at midspan.**

**Appendix II**  
**Site Location Photographs**



**South approach to bridge looking North.**




**North approach to bridge looking South.**



**West side of bridge.**



**East side of bridge.**



**SE corner of abutment showing rocker connection and C-I-P concrete abutment.**



**SW corner of abutment showing rocker connection and P-I-C concrete abutment.**



**Steel angle iron railing affixed to truss members.**

## Appendix III MN/DOT Structure Inventory and Bridge Inspection Reports

### Mn/DOT Structure Inventory Report

Bridge ID: 5034 CR 83 over REDWOOD RIVER

Date: 05/10/2011

+ GENERAL +	+ ROADWAY +	+ INSPECTION +
Agency Br. No. S1	Bridge Match ID (TIS) 1	Deficient Status ADEQ
District 8 Maint. Area	Roadway O/U Key 1-ON	Sufficiency Rating 56.4
County 42 - LYON	Route Sys/Nbr CNTY 83	Last Inspection Date 11-02-2010
City	Roadway Name or Description	Inspection Frequency 12
Township LYONS	CR 83	Inspector Name LYON
Desc. Loc. 2.1 MI SW OF JCT CSAH 5	Roadway Function MAINLINE	Structure P-LOAD POSTED
Sect., Twp., Range 05 - 110N - 42W	Roadway Type 2 WAY TRAF	<b>+ NBI CONDITION RATINGS +</b>
Latitude 44d 22m 11.95s	Control Section (TH Only)	Deck 7
Longitude 95d 55m 28.11s	Ref. Point (TH Only)	Superstructure 5
Custodian COUNTY	Date Opened to Traffic 12-01-1990	Substructure 7
Owner COUNTY	Detour Length 1 mi.	Channel 7
Inspection By LYON COUNTY	Lanes 2 Lanes ON Bridge	Culvert N
BMU Agreement	ADT (YEAR) 40 (2005)	<b>+ NBI APPRAISAL RATINGS +</b>
Year Built 1931	HCADT	Structure Evaluation 4
Year Fed Rehab	Functional Class. RURAL LOCAL	Deck Geometry 6
Year Remodeled 1990	<b>+ RDWY DIMENSIONS +</b>	Underclearances N
Temp	If Divided NB-EB SB-WB	Waterway Adequacy 9
Plan Avail. COUNTY	Roadway Width 27.0 ft	Approach Alignment 9
<b>+ STRUCTURE +</b>	Vertical Clearance	<b>+ SAFETY FEATURES +</b>
Service On HIGHWAY	Max. Vert. Clear.	Bridge Railing 0-SUBSTANDARD
Service Under STREAM	Horizontal Clear.	GR Transition 0-SUBSTANDARD
Main Span Type STEEL LOW TRUSS	Lateral Clr. - L/Rt	Appr. Guardrail 0-SUBSTANDARD
Main Span Detail WARREN W/VERT	Appr. Surface Width 24.0 ft	GR Termini 0-SUBSTANDARD
Appr. Span Type	Roadway Width 27.0 ft	<b>+ IN DEPTH INSP. +</b>
Appr. Span Detail	Median Width	Frac. Critical Y 24 mo 09/2010
Skew	<b>+ MISC. BRIDGE DATA +</b>	Underwater
Culvert Type	Structure Flared NO	Pinned Asbly.
Barrel Length	Parallel Structure NONE	Spec. Feat.
Number of Spans	Field Conn. ID RIVETED	<b>+ WATERWAY +</b>
MAIN: 1 APPR: 0 TOTAL: 1	Cantilever ID	Drainage Area
Main Span Length 73.0 ft	Foundations	Waterway Opening 750 sq ft
Structure Length 75.0 ft	Abut. STEEL - PILE BENT	Navigation Control NO PRMT REQD
Deck Width 28.0 ft	Pier N/A	Pier Protection NOT APPL
Deck Material C-I-P CONCRETE	Historic Status NOT ELIGIBLE	Nav. Vert./Horz. Clr.
Wear Surf Type MONOLITHIC CONC	On - Off System OFF	Nav. Vert. Lift Bridge Clear.
Wear Surf Install Year	<b>+ PAINT +</b>	MN Scour Code L-STBL;LOW RISK
Wear Course/Fill Depth	Year Painted Pct. Unsound	Scour Evaluation Year 2002
Deck Membrane NONE	Painted Area	<b>+ CAPACITY RATINGS +</b>
Deck Protect. N/A	Primer Type	Design Load H 15
Deck Install Year	Finish Type	Operating Rating HS 15.40
Structure Area 2,100 sq ft	<b>+ BRIDGE SIGNS +</b>	Inventory Rating HS 9.20
Roadway Area 2,024 sq ft	Posted Load VEHICLE & SEMI	Posting VEH: 24 SEMI: 36 DBL: 36
Sidewalk Width - L/R	Traffic NOT REQUIRED	Rating Date 02-16-2010
Curb Height - L/R 0.83 ft 0.83 ft	Horizontal NOT REQUIRED	Mn/DOT Permit Codes
Rail Codes - L/R 32 32	Vertical NOT APPLICABLE	A: N B: N C: N

05/10/2011

Page 1 of 3

Mn/DOT BRIDGE INSPECTION REPORT

Inspected by: LYON COUNTY

BRIDGE 5034 CR 83 OVER REDWOOD RIVER

INSP. DATE: 11-02-2010

County: LYON Location: 2.1 MI SW OF JCT CSAH 5 Length: 75.0 ft  
 City: Route: CNTY 83 Ref. Pt.: 000+00.740 Deck Width: 28.0 ft  
 Township: LYONS Control Section: Maint. Area: Rdwy. Area / Pct. Unsnd: 2,024 sq ft  
 Section: 05 Township: 110N Range: 42W Local Agency Bridge Nbr: S1 Paint Area/ Pct. Unsnd:  
 Span Type: STEEL LOW TRUSS Culvert N/A  
 NBI Deck: 7 Super: 5 Sub: 7 Chan: 7 Culv: N Open, Posted, Closed: LOAD POSTED Postings: 24 - 36 - 36  
 Appraisal Ratings - Approach: 9 Waterway: 9 MN Scour Code: L-STBL;LOW RISK Def. Stat: ADEQ Suff. Rate: 56.4  
 Required Bridge Signs - Load Posting: VEHICLE & SEMI Traffic: NOT REQUIRED  
 Horizontal: NOT REQUIRED Vertical: NOT APPLICABLE

STRUCTURE UNIT: 0

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
32	TIMBER DECK-BIT O/L	2	11-02-2010 11-05-2009	2,100 SF 2,099 SF	0 2,099	2,100 0	0 0	0 0	N/A N/A
Notes: 2010 moderate cacking crack at floor beam 12"x1" hole at end of deck									
303	ASSEMBLY DECK JOINT	1	11-02-2010	2 LF	0	2	0	N/A	N/A
Notes: Sliding plates at both abutments has surface corrosion									
407	BITUMINOUS APPROACH	1	11-02-2010 11-05-2009	2 EA 2 EA	0 2	2 0	0 0	0 0	N/A N/A
Notes: 2008 approach settling 2010 West settle 1.75" East end 1.5"									
334	METAL RAIL-COATED	2	11-02-2010 11-05-2009	151 LF 151 LF	0 0	151 151	0 0	0 0	0 0
Notes: 2002 needs paint									
113	PAINT STEEL STRINGER	1	11-02-2010 11-05-2009	899 LF 899 LF	0 0	0 0	899 899	0 0	0 0
Notes: 2002 needs paint minor section loss 2007 minor debris damage									
121	P/STL THRU TRUSS/BOT	1	11-02-2010 11-05-2009	148 LF 148 LF	0 0	0 0	148 148	0 0	0 0
Notes: 2002 needs paint minor section loss 2010 Extensive paint loss and bent lower chord on So truss									
126	P/STL THRU TRUSS/TOP	1	11-02-2010 11-05-2009	148 LF 148 LF	0 0	0 0	148 148	0 0	0 0
Notes: 2002 needs paint minor section loss 2010 60% paint gone 1/8" pitting on L6-U7S									
152	PAINT STL FLOORBEAM	1	11-02-2010 11-05-2009	128 LF 128 LF	1 0	0 0	103 0	24 128	0 0
Notes: 2002 needs paint minor section loss 2010 The bottom flanges of floor beam 0 & 10 have distortions of up to 2". needs paint with flaking rust on bottom flange of floor beams. 1/16" pack rust and minor section loss at floor beam.									
423	GUSSET PLATE (PAINT)	1	11-02-2010	22 EA	0	0	19	3	0
Notes: 2010 24% loss of thickness over a 17" x2.5" area ata L4N. 24% loss over a 6" x 4" area at L4N exterior betwn L4-U4N and diag L4-U3N. Approx. 1/8" loss at L4N interior betwn L4-U4N and diag L4-U3N. 20% loss over a 8"line at L6N interior along L6-U6N									
380	SECONDARY ELEMENTS	1	11-02-2010	1 EA	1	0	0	0	N/A
Notes:									

05/10/2011

Page 2 of 3

**Mn/DOT BRIDGE INSPECTION REPORT**

Inspected by: LYON COUNTY

**BRIDGE 5034 CR 83 OVER REDWOOD RIVER****INSP. DATE: 11-02-2010****STRUCTURE UNIT: 0**

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
311	EXPANSION BEARING	2	11-02-2010 11-05-2009	2 EA 2 EA	0 0	2 2	0 0	N/A N/A	N/A N/A
	Notes: ROCKERS NEED REALIMENT SEVERLY OUT OF ALIGNMENT 2007 rockers realiged- brock a corner off when realiging. 2010 So. Rocker 7/8 out of alg. to south and north bearing 3/8 out of alg. south								
313	FIXED BEARING	1	11-02-2010 11-05-2009	2 EA 2 EA	0 0	2 2	0 0	N/A N/A	N/A N/A
	Notes: 2010 no anchor rods were placed.								
215	CONCRETE ABUTMENT	2	11-02-2010 11-05-2009	46 LF 56 LF	46 56	0 0	0 0	0 0	N/A N/A
	Notes: < none >								
387	CONCRETE WINGWALL	2	11-02-2010 11-05-2009	4 EA 4 EA	4 0	0 4	0 0	0 0	N/A N/A
	Notes: < none >								
357	PACK RUST	1	11-02-2010	1 EA	0	1	0	0	N/A
	Notes: 2010 pack rust on all panel points. 1/8 "bow pack rust on U7S int,L10Sext, L2N int								
361	SCOUR	2	11-02-2010 11-05-2009	1 EA 1 EA	1 1	0 0	0 0	N/A N/A	N/A N/A
	Notes: 0 - Stable for scour. Additional action required.								
362	TRAFFIC IMPACT	1	11-02-2010	1 EA	1	0	0	N/A	N/A
	Notes: 2010bottom chord from L2-L9 on the south truss is rolledunder 6" 1" by 6" bend in L9-L10s due to impact								
363	SECTION LOSS	1	11-02-2010	1 EA	1	0	0	0	N/A
	Notes: 1/8" thickness loss at both interior and exterior of diagonal L8-U7S connection at L8S. 1/8 loss at exterior member of diagonal L2-U1N at L2N								
964	CRITICAL FINDING	2	11-02-2010 11-05-2009	1 EA 1 EA	1 1	0 0	N/A N/A	N/A N/A	N/A N/A
	Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.								
966	FRACTURE CRITICAL	2	11-02-2010 11-05-2009	1 EA 1 EA	1 1	0 0	0 0	N/A N/A	N/A N/A
	Notes: Do Not Remove. See in-depth report for location of F/C members.								
981	SIGNING	2	11-02-2010 11-05-2009	1 EA 1 EA	1 1	0 0	0 0	0 0	0 0
	Notes: < none >								
985	SLOPES	2	11-02-2010 11-05-2009	1 EA 1 EA	1 1	0 0	0 0	N/A N/A	N/A N/A
	Notes: < none >								

05/10/2011

Page 3 of 3

**Mn/DOT BRIDGE INSPECTION REPORT**

Inspected by: LYON COUNTY

**BRIDGE 5034 CR 83 OVER REDWOOD RIVER**

**INSP. DATE: 11-02-2010**

STRUCTURE UNIT: 0

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
967	GUSSET DISTORTION	1	11-02-2010	1 EA	0	1	0	0	N/A

Notes: 2010 gusset plates bowed due to fit up at 1/8" at L2Sext, L4S ext, L8S int., L4N int. U7S int. is bowed 1/8 " due to pack rust and L2N int. is bowed 1/8" due to fit up and pack rust. L10S is bowed 1/8" due to rust. these gussets are bowed 1/16" due to fit up L0n int, L4Sint, L4N ext. and int. L6N est. L8S ext.

General Notes: > smj & ckm  
 2002smj 2003 smj & ckm  
 2004 smj 2005smj 2006 smj  
 2007 smj MNDOT inspected the bridge couldn't fine any major problems 2008smj 2009smj

\_\_\_\_\_  
 Inspector's Signature

\_\_\_\_\_  
 Reviewer's Signature / Date

## Appendix IV

### Laboratory Analysis Reports



EMSL Analytical, Inc.

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: minneapolis@emsl.com

Attn: **Denice Cliff**  
**Institute For Environmental Assessment**  
**9201 West Broadway**  
**Suite 600**  
**Brooklyn Park, MN 55445**

Customer ID: IFEA50  
 Customer PO:  
 Received: 08/30/11 8:00 AM  
 EMSL Order: 351103778

Fax: (763) 315-7920 Phone: (763) 315-7900  
 Project: 1667-1112053, Lyon County Bridge #5034, Ernest G. Flata

EMSL Proj:

#### Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B\*7000B)

Lab ID:	Analyzed	RDL	Lead Concentration	Notes
0001	6/30/2011	0.010 % wt	44 % wt	Site: Abut Girder near Pin Connection @ SW Cor. <i>Collected: 6/29/2011</i>
<i>Client Sample LP-1</i>				
0002	6/30/2011	0.010 % wt	38 % wt	Site: Stringer beam near Pin Connection @ NE Cor. <i>Collected: 6/29/2011</i>
<i>Client Sample LP-2</i>				
0003	6/30/2011	0.010 % wt	42 % wt	Site: Truss member downstream side @ mid span <i>Collected: 6/29/2011</i>
<i>Client Sample LP-3</i>				
0004	6/30/2011	0.010 % wt	42 % wt	Site: Gusset Plate @ SW Cor <i>Collected: 6/29/2011</i>
<i>Client Sample LP-4</i>				
0005	6/30/2011	0.010 % wt	42 % wt	Site: Gusset Plate NE Cor <i>Collected: 6/29/2011</i>
<i>Client Sample LP-5</i>				
0006	6/30/2011	0.010 % wt	39 % wt	Site: Top truss member, Southside @ mid span <i>Collected: 6/29/2011</i>
<i>Client Sample LP-6</i>				

Initial report from 08/30/2011 14:08:47

Rachel Travis, Laboratory Manager  
 or other approved signatory

Reporting limit is 0.01 % wt. The QC data associated with these results included in this report meet the method QC requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. \* slight modifications to methods applied.

Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn A11A-LAP, LLC ELLAP 163162

**Appendix V**  
**Chain of custody Documents**

June 27, 2011

Denice Cliff  
Institute for Environment Assessment, Inc.  
9201 West Broadway, Suite 600  
Brooklyn Park, MN 55445

Re: Testing for the presence of lead in paint; Samples LP-1 thru LP-6.  
Lyon County Bridge # 5034

Dear Ms. Cliff:

Enclosed are six samples, LP-1 thru LP-6 which are to be tested for the presence of lead. All samples are in zip lock bags and labeled with sample numbers, dates of sampling, and project identification. Please forward the test results and required chain of custody forms to:

Ernest G. Fiala, PE  
118 W. 3<sup>rd</sup> St.  
Redwood Falls, MN 56283

[ernie.fiala@gmail.com](mailto:ernie.fiala@gmail.com)

507-637-2492  
507-430-3600 Cell

Lyon County intends to demolish this structure as soon as possible and has requested a rush on the testing if at all possible. Please advise by E-mail above if this is possible. Also, would you please forward a copy of your most recent NVLAP lab certifications so I may update my files. All fees incurred should be billed to the above. Should you have any questions or require additional information, please contact me at any of the above.

Sincerely,

  
Ernest G. Fiala, P.E.



# CHAIN OF CUSTODY

5778

2538

Page \_\_\_ of \_\_\_

Client # None Project # 1112-053 Building Name Lyon County Bridge #5034  
 Client Ernst G. Fiala Project Name Lead Sampling Contact Person Ernst G. Fiala  
 Address \_\_\_\_\_ Contact Person Phone \_\_\_\_\_  
 Other Information \_\_\_\_\_  
 Verbal results relayed to Dennis Phone, Fax No. or E-Mail \_\_\_\_\_  
 Verbal results relayed by \_\_\_\_\_ Date \_\_\_\_\_  
 Analysis location:  On Site  Lab  Regional Office  Other EMSL

Sample #	Work Area or Phase #	Comments / Location	Sample type or Material code	Volume	Matrix type			Analysis requested			Filter type				
					Air	Bulk	Dust	PCM	PLM	TEM	Other	MCE	8 um	5 um	
LP-1		Abut Girder near Pin Connection @ SW Cor.			<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
LP-2		Stringer beam near Pin Connection @ NE Cor			<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
LP-3		Truss member downstream side @ mid span			<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
LP-4		Gusset Plate @ SW Cor			<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
LP-5		Gusset Plate NE Cor			<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
LP-6		Top truss member, Southside @ mid span			<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

The MN Department of Health Alternative Indoor Air Standard for this project is: \_\_\_\_\_  
 Samples by Dennis Date 6/29/11 Time \_\_\_\_\_  
 Received by Dennis Date 6/29/11 Time \_\_\_\_\_  
 Batch Number: \_\_\_\_\_  
 Received by lab AKJ Date 01/20/11 Time 8:00 AM  
 Analysis by \_\_\_\_\_  
 Samples Acceptable?  Yes  No  
 Entered by \_\_\_\_\_ Date \_\_\_\_\_  
 Delivered by \_\_\_\_\_ Date \_\_\_\_\_

© IEA, Inc. 2010

## Appendix VI

### Laboratory Accreditations



### AIHA Laboratory Accreditation Programs, LLC

#### SCOPE OF ACCREDITATION

EMSL Analytical, Inc.  
14375 23rd Avenue North, Minneapolis, MN 55447

Laboratory ID: 163162  
Issue Date: 02/01/2011

The laboratory is approved for those specific field(s) of testing/methods listed in the table below. Clients are urged to verify the laboratory's current accreditation status for the particular field(s) of testing/Methods, since these can change due to proficiency status, suspension and/or revocation. A complete listing of currently accredited Environmental Lead laboratories is available on the AIHA-LAP, LLC website at: <http://www.aihaaccreditedlabs.org>

The EPA recognizes the AIHA-LAP, LLC ELLAP program as meeting the requirements of the National Lead Laboratory Accreditation Program (NLLAP) established under Title X of the Residential Lead-Based Paint Hazard Reduction Act of 1992 and includes paint, soil and dust wipe analysis. Air analysis is not included as part of the NLLAP.

#### Environmental Lead Laboratory Accreditation Program (ELLAP)

Initial Accreditation Date: 09/01/2010


Field of Testing (FoT)	Method	Method Description <i>(for internal methods only)</i>
Airborne Dust	NIOSH 7082	
Paint	EPA SW-846 7000B	
	EPA SW-846 3050B	
Settled Dust by Wipe	EPA SW-846 7000B	
	EPA SW-846 3050B	
Soil	EPA SW-846 7000B	
	EPA SW-846 3050B	

The laboratory participates in the following AIHA-LAP, LLC-approved proficiency testing programs:

- ✓ Paint
- ✓ Soil
- ✓ Settled Dust by Wipe
- ✓ Airborne Dust

Effective: 4/24/09  
Scope\_ELLAP\_R4  
Page 1 of 1

**Appendix VII**  
**Inspector's Licensure and Certification**



### Appendix VIII



#### Minnesota Pollution Control Agency Notification of Intent to Perform a Bridge Demolition for Mn/DOT Operations.



Type of Notification:  Original  Amended  Project Cancellation  
Notification must be postmarked or received ten (10) WORKING days before demolition begins.

**Demolition Contractor:**

Name: \_\_\_\_\_  
Address: \_\_\_\_\_  
\_\_\_\_\_  
City, State, Zip: \_\_\_\_\_  
Contact Person: \_\_\_\_\_  
Phone Number(s): \_\_\_\_\_

**Bridge Information:**

Bridge Name: \_\_\_\_\_  
Mile Point/Trunk Highway: \_\_\_\_\_  
Miles and direction (N.E.W.S) From Nearest Town: \_\_\_\_\_  
County: \_\_\_\_\_  
Project Engineer Phone Number(s): \_\_\_\_\_  
Age of Brdg. (years): \_\_\_\_\_ Size of Brdg. (sq. ft.): \_\_\_\_\_  
Type of Bridge: \_\_\_\_\_

**Bridge Owner:**

Name: \_\_\_\_\_  
Address: \_\_\_\_\_  
\_\_\_\_\_  
City, State, Zip: \_\_\_\_\_  
Contact person: \_\_\_\_\_  
Phone Number(s): \_\_\_\_\_

Suspect Materials to be checked for asbestos: pipes, asphalt underlay, spray-on and joint compounds.  
Dates when demolition will Begin \_\_\_\_\_ & End \_\_\_\_\_  
Both Beginning and Ending dates should be amended in writing as necessary to reflect current project dates.

**There is no Asbestos Containing Material (ACM) present in the structure to be demolished**

1. Company and/or individual that conducted the bridge inspection or record review, certification#, and the procedure used to determine the presence or absence of ACM (including analytic method): *Prior to demolition all bridges must be inspected by an MDH certified asbestos inspector.* \_\_\_\_\_

2. Description of planned demolition and the specific method(s) that will be used: \_\_\_\_\_

Demolition Material will be recycled on site or a metal scrap recycler, Material not recycled will be sent to:

3. Demolition Waste Transporter(s) Information:  
Transporter Name: \_\_\_\_\_  
Transporter Contact: \_\_\_\_\_  
Transporter Address: \_\_\_\_\_  
City, State, Zip: \_\_\_\_\_  
Phone Number: \_\_\_\_\_

4. Demolition Waste Disposal Information:  
Landfill Name: \_\_\_\_\_  
Owner/Operator: \_\_\_\_\_  
Address/Location: \_\_\_\_\_  
City, State, Zip: \_\_\_\_\_  
Phone Number: \_\_\_\_\_

5. I certify that the above information is correct and I am a bonafide representative of the demolition contractor or bridge owner and have authority to enter into agreements for my employer. In event that unexpected asbestos containing material is found, the material will be removed by a MDH certified asbestos abatement contractor.

Signature of Contractor, Owner Agent \_\_\_\_\_ Date \_\_\_\_\_

Send to: Minnesota Pollution Control Agency  
Regional Environmental Management Division  
520 Lafayette Road North  
St. Paul, MN 55155-4194

For questions call:  
651-296-6300  
1-800-657-3864  
FAX: 651-215-1593

**PCB Removal Information** Polychlorinated Biphenyls (PCBs) will be removed from the bridge prior to demolition.

**Mercury Removal Information** Material containing mercury will be removed from the bridge prior to demolition.

(Notification of Intent to Perform a Demolition form 1)

Revised 08/04

CC: Mark Vogel, OES, MS 620

**Appendix IX**  
**Notification Form on Transfer of Bridge Steel**

NOTIFICATION FORM ON DISPOSAL OF BRIDGE STEEL

The Contractor is required to provide certain information on disposal of bridge steel which has been painted with lead-based paint. By signing this document, the Contractor certifies that information supplied by the Contractor is correct and that the Contractor is familiar with proper handling and disposal of materials with lead-based paint. This information must be furnished to the Project Engineer a minimum of 30 days prior to removal of the bridge steel from the project site. Any change in method or location of disposal would require resubmittal and a 30 day notice.

Mn/DOT Project No. \_\_\_\_\_ Bridge No. \_\_\_\_\_

Description of Bridge Steel \_\_\_\_\_

Paint System is Mn/DOT Spec. \_\_\_\_\_  
 (Primer) (Top Coat)

Project Engineer: \_\_\_\_\_

Contractor/Subcontractor: \_\_\_\_\_  
 (Name, mailing address, telephone no.)

I \_\_\_\_\_ certify that the following information is correct:  
 (print name of authorized representative)

The above bridge steel will be disposed of by the following method(s): \_\_\_\_\_  
 (list name, address and telephone no. of recipient, estimated delivery date, and intended use.)

I also certify that \_\_\_\_\_ is familiar with  
 (Contractor/Subcontractor name)  
 the requirements in OSHA 29 CFR 1926.62 relating to lead, precautions to be taken when working with lead, and proper handling and disposal of materials with lead-based paint systems and that \_\_\_\_\_ has been notified of the presence of lead-based paint.  
 (name of recipient)

\_\_\_\_\_  
 (signature) (date)

Received by Project Engineer/Inspector: \_\_\_\_\_  
 (date) (signature)

cc: Project File  
 Office of Environmental Services

**Appendix X**  
**Notification Form on Ownership Transfer**  
**of Treated Wood**

1 of 2 pages

NOTIFICATION FORM ON OWNERSHIP TRANSFER OF TREATED WOOD

The prospective buyer identified below has expressed interest in obtaining treated wood from Mn/DOT for reuse/recycling. Treated wood can include, but is not limited to: copper chromium arsenic (CCA), ammoniacal copper quat (ACQ), copper azole, ammoniacal copper citrate, creosote, and pentachlorophenol (PCP or penta). By signing this document, the buyer certifies that he or she is familiar with proper handling and disposal of this material. The buyer must complete this form to Mn/DOT's satisfaction prior to removal of any treated wood. Any change in the method or location of re-use of the materials would require re-submittal and approval.

Source of treated wood: \_\_\_\_\_

Mn/DOT Contract: \_\_\_\_\_

Buyer: \_\_\_\_\_  
(name, company, mailing address, telephone number)

I \_\_\_\_\_ certify that the following information is correct:  
(Print name of authorized buyer)

The above treated wood will be reused in the following manner: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

I also certify that \_\_\_\_\_ is familiar with Local, State and  
(buyer name)

Federal requirements, including the Minnesota Pollution Control Agency fact sheet "Treated Wood: Use, Disposal and Alternatives for Businesses", regarding proper handling and disposal of treated wood and the buyer has been notified of this.

\_\_\_\_\_  
(buyers signature)

\_\_\_\_\_  
(date)

Received by Mn/DOT representative: \_\_\_\_\_  
(print name)

\_\_\_\_\_  
(signature)

\_\_\_\_\_  
(date)

cc: District File  
Office of Environmental Services (Mail stop 620)

