

**ASBESTOS & REGULATED WASTE
ASSESSMENT REPORT**

**BRIDGE# 5101A
LYONS TOWNSHIP
LYON COUNTY, MN**



Prepared for:

**Lyon County Highway Department
Suhail Kanwar, P.E., County Engineer**

September 22, 2011

TABLE OF CONTENTS

	Page
Site Specifics & Certifications	3
Summary of all Asbestos & Regulated Waste & Actions Required for this Demolition	4
2.1 Asbestos Summary	4
2.2 Lead Summary	4
2.3 Regulated Waste Summary	4
Appendix I Sample location Photographs	5-7
Appendix II Site Location Photographs	8-11
Appendix III MN/DOT Structure Inventory Report	12-15
Appendix IV Laboratory Analysis Report	16
Appendix V Chain of Custody Documents	17-18
Appendix VI Laboratory Accreditations	19-20
Appendix VII Inspectors Licensure and Certification	21
Appendix VIII MPCA Notification of Intent to Perform a Bridge Demolition for MN/DOT Operations Form	22
Appendix IX Notification Form on Transfer of Bridge Steel	23
Appendix X Notification Form on Ownership Transfer of Treated Wood	24-25

Site Specifics & Certifications

Bridge No.: 5101A

Location: On CR 83 over Redwood River, 2.6 Mi. Southwest of Jct. CSAH 5, in Lyons Township, Lyon County, Minnesota; Sec 05, T110N, R42W.

Type of Structure: Bridge # 5101A is a 61.3' x 30.0', single span, steel Warren low truss bridge built in 1931.

Railing: Steel angle iron affixed to truss members.

Decking: Timber.

Superstructure: Treated timber deck on steel stringers, bituminous surface with no membrane present per MN/DOT Structure Inventory Report dated 05/10/2011, and site inspection 06/15/2011.

Substructure: P-I-C concrete each abutment. See MN/DOT Structure Inventory Report dated 05/10/2011 and Site Photographs Appendix II.


Current Owner: Lyon County.

Disposition of Structure: Demolition

Licensure: MDH Certified Asbestos Inspector, Ernest G. Fiala, P.E. Conducted this Inspection (See Appendix IV).

Certification: The undersigned certifies that this asbestos inspection was performed on June 15, 2011, in compliance with MN Rules 4620.3460.

This report was compiled under my direct supervision. I have reviewed the report's contents and find it to meet MN/DOT requirements as described in the "Asbestos & Regulated Waste Manual for Structure Demolition or Relocations for Construction Projects."



**Ernest G. Fiala, P.E. Reg. No. 18480
MDH Asbestos Inspector #AI10135**

Summary of all Asbestos & Regulated Waste & Actions Required for this Demolition

Based on a field inspection, the following conclusions are summarized for Asbestos & Regulated Waste Assessment. Applicable items listed below should be removed and/or stabilized prior to demolition of Bridge # 5101A.

2.1 Asbestos Summary

No asbestos or asbestos containing materials were found on structure.

2.2 Lead Summary

Sample LP-1 was taken from the abutment girder near the rocker pin assembly at the SW corner of bridge and indicated a lead presence of 30%.

Sample LP-2 was taken from the pin assembly at the SE corner of bridge and indicated a lead presence of 17%.

Sample LP-3 was taken from the railing at the SW corner of bridge and indicated a lead presence of 27%.

Sample LP-4 was taken from the gusset plate assembly at the NE corner of bridge and indicated a lead presence of 40%.

Sample LP-5 was taken the truss member at the NW corner of bridge and indicated a lead presence of 37%.

Sample LP-6 was taken from the truss member at the NE corner of bridge and indicated a lead presence of 29%.

Pictures of all sample locations are included in Appendix I.

2.3 Regulated Waste Summary

The following Regulated Waste was observed on or in the vicinity of the bridge.

2.3.1 Mercury – None

2.3.2 PCBs – None

2.3.3 CFCs – None

2.3.4 Treated wood –None

2.3.5 Household Hazardous Waste - None.


2.3.6 White Goods - None.

2.3.7 Solid Waste - None.

Appendix I
Sample Location Photographs



**Sample LP-1. Lead paint sample from abutment girder near rocker pin assembly.
SW corner of bridge.**




Sample LP-2. Lead paint sample from pin assembly at the SE corner of bridge.



Sample LP-3. Lead paint sample from railing at SW corner of bridge.



Sample LP-4. Lead paint sample from gusset plate at NE corner of bridge.



Sample LP-5. Lead paint sample from truss member at NW corner of bridge.



Sample LP-6. Lead paint sample from truss member at NE corner of bridge.

Appendix II
Site Location Photographs



South approach to bridge looking North.



North approach to bridge looking South.



West side of bridge.



East side of bridge.



SE corner of abutment showing pin connection and C-I-P concrete abutment.



SW corner of abutment showing rocker connection and P-I-C concrete abutment.



Steel angle iron railing affixed to truss members.

Appendix III

MN/DOT Structure Inventory and

Bridge Inspection Reports

Mn/DOT Structure Inventory Report

Bridge ID: 5101A CR 83 over REDWOOD RIVER

Date: 05/10/2011

+ GENERAL +	+ ROADWAY +	+ INSPECTION +
Agency Br. No. S1	Bridge Match ID (TIS) 1	Deficient Status ADEQ
District 8 Maint. Area	Roadway O/U Key 1-ON	Sufficiency Rating 56.7
County 42 - LYON	Route Sys/Nbr CNTY 83	Last Inspection Date 11-02-2010
City	Roadway Name or Description	Inspection Frequency 12
Township LYONS	CR 83	Inspector Name LYON
Desc. Loc. 2.6 MI SW OF JCT CSAH 5	Roadway Function MAINLINE	Structure P-LOAD POSTED
Sect., Twp., Range 05 - 110N - 42W	Roadway Type 2 WAY TRAF	+ NBI CONDITION RATINGS +
Latitude 44d 21m 50.41s	Control Section (TH Only)	Deck 7
Longitude 95d 55m 30.88s	Ref. Point (TH Only)	Superstructure 5
Custodian COUNTY	Date Opened to Traffic 11-01-1989	Substructure 8
Owner COUNTY	Detour Length 1 mi.	Channel 8
Inspection By LYON COUNTY	Lanes 2 Lanes ON Bridge	Culvert N
BMU Agreement	ADT (YEAR) 40 (2005)	+ NBI APPRAISAL RATINGS +
Year Built 1931	HCA DT	Structure Evaluation 4
Year Fed Rehab	Functional Class. RURAL LOCAL	Deck Geometry 7
Year Remodeled 1989	+ RDWY DIMENSIONS +	Underclearances N
Temp	If Divided NB-EB SB-WB	Waterway Adequacy 8
Plan Avail. NO PLAN	Roadway Width 28.0 ft	Approach Alignment 8
+ STRUCTURE +	Vertical Clearance	+ SAFETY FEATURES +
Service On HIGHWAY	Max. Vert. Clear.	Bridge Railing 0-SUBSTANDARD
Service Under STREAM	Horizontal Clear.	GR Transition N-NOT REQUIRED
Main Span Type STEEL LOW TRUSS	Lateral Cir. - L/Rt	Appr. Guardrail N-NOT REQUIRED
Main Span Detail WARREN W/VERT	Appr. Surface Width 24.0 ft	GR Termini N-NOT REQUIRED
Appr. Span Type	Roadway Width 28.0 ft	+ IN DEPTH INSP. +
Appr. Span Detail	Median Width	Frac. Critical Y 24 mo 09/2010
Skew	+ MISC. BRIDGE DATA +	Underwater
Culvert Type	Structure Flared NO	Pinned Asbly.
Barrel Length	Parallel Structure NONE	Spec. Feat.
Number of Spans	Field Conn. ID RIVETED	+ WATERWAY +
MAIN: 1 APPR: 0 TOTAL: 1	Cantilever ID	Drainage Area
Main Span Length 60.0 ft	Foundations	Waterway Opening 300 sq ft
Structure Length 61.3 ft	Abut.	Navigation Control NO PRMT REQD
Deck Width 30.0 ft	Pier N/A	Pier Protection NOT APPL
Deck Material TIMBER	Historic Status NOT ELIGIBLE	Nav. Vert./Horz. Cir.
Wear Surf Type BITUMINOUS	On - Off System OFF	Nav. Vert. Lift Bridge Clear.
Wear Surf Install Year	+ PAINT +	MN Scour Code G-FND UNKN; EVAL
Wear Course/Fill Depth 0.20 ft	Year Painted Pct. Unsound 40 %	Scour Evaluation Year
Deck Membrane NONE	Painted Area	+ CAPACITY RATINGS +
Deck Protect. NONE	Primer Type LEAD, IRON OXIDE	Design Load UNKN
Deck Install Year	Finish Type VINYL	Operating Rating HS 14.00
Structure Area 1,839 sq ft	+ BRIDGE SIGNS +	Inventory Rating HS 8.40
Roadway Area 1,711 sq ft	Posted Load VEHICLE & SEMI	Posting VEH: 22 SEMI: 40 DBL: 40
Sidewalk Width - L/R	Traffic NOT REQUIRED	Rating Date 02-16-2010
Curb Height - L/R	Horizontal NOT REQUIRED	Mn/DOT Permit Codes
Rail Codes - L/R 32 32	Vertical NOT APPLICABLE	A: N B: N C: N

05/10/2011

Page 1 of 3

Mn/DOT BRIDGE INSPECTION REPORT

Inspected by: LYON COUNTY

BRIDGE 5101A CR 83 OVER REDWOOD RIVER

INSP. DATE: 11-02-2010

County: LYON	Location: 2.6 MI SW OF JCT CSAH 5	Length: 61.3 ft
City:	Route: CNTY 83 Ref. Pt.: 000+00.200	Deck Width: 30.0 ft
Township: LYONS	Control Section: Maint. Area:	Rdwy. Area / Pct. Unsnd: 1,711 sq ft
Section: 05 Township: 110N Range: 42W	Local Agency Bridge Nbr: S1	Paint Area/ Pct. Unsnd: 40 %
Span Type: STEEL LOW TRUSS		Culvert N/A
NBI Deck: 7 Super: 5 Sub: 8 Chan: 8 Culv: N	Open, Posted, Closed: LOAD POSTED	Postings: 22 - 40 - 40
Appraisal Ratings - Approach: 8 Waterway: 8	MN Scour Code: G-FND UNKN;EVAL	Def. Stat: ADEQ Suff. Rate: 56.7
Required Bridge Signs - Load Posting: VEHICLE & SEMI	Traffic: NOT REQUIRED	
Horizontal: NOT REQUIRED	Vertical: NOT APPLICABLE	

STRUCTURE UNIT: 0

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
32	TIMBER DECK-BIT O/L	2	11-02-2010 11-05-2009	1,839 SF 1,841 SF	0 1,841	1,839 0	0 0	0 0	N/A N/A
Notes: 2010 the deck has moderate transverse cracking at every floor beam with longit. cracks between									
303	ASSEMBLY DECK JOINT	1	11-02-2010	56 LF	0	56	0	N/A	N/A
Notes: 2010 minor corrosion									
407	BITUMINOUS APPROACH	1	11-02-2010 11-05-2009	2 EA 2 EA	0 2	2 0	0 0	0 0	N/A N/A
Notes: 2010 minor settlement at bridge joints									
334	METAL RAIL-COATED	2	11-02-2010 11-05-2009	120 LF 121 LF	0 0	112 121	8 0	0 0	0 0
Notes: 2010 Impack damage North end									
113	PAINT STEEL STRINGER	1	11-02-2010 11-05-2009	720 LF 719 LF	0 0	720 719	0 0	0 0	0 0
Notes: 2002 needs paint minor rust 2010									
121	P/STL THRU TRUSS/BOT	1	11-02-2010 11-05-2009	120 LF 121 LF	0 0	0 0	60 121	60 0	0 0
Notes: 2002 needs paint minor rusting. minor impact damage due to flood debris. 2010 peeling paint, surface corrosion, flaking rust and section loss on lower chord angles at L2E inside top vertical leg, L4E insided bottom vertical leg, L2W inside top and bottom vertical legs, L4W outside tip and bottom vertical legs. less than 10% section loss									
126	P/STL THRU TRUSS/TOP	1	11-02-2010 11-05-2009	120 LF 121 LF	0 0	0 62	110 59	10 0	0 0
Notes: > 2002 needs paint minor rust									
152	PAINT STL FLOORBEAM	1	11-02-2010 11-05-2009	147 LF 72 LF	0 0	0 72	147 0	0 0	0 0
Notes: 2002 needs paint minor rust									
423	GUSSET PLATE (PAINT)	1	11-02-2010	18 EA	0	3	15	0	0
Notes: 2010 CS2 rating = U1E,U1W, & U5E CS3= minor section loss on L2E,L6E,L2W, AND L6W (total loss of 5%) 2.5" tear on bottom of L0E out side gusset. pack rust on bottom cord at L2E north side.125, L2W north side .5 and L6W .375" south side									
380	SECONDARY ELEMENTS	1	11-02-2010	1 EA	1	0	0	0	N/A
Notes:									

05/10/2011

Mn/DOT BRIDGE INSPECTION REPORTInspected by: LYON COUNTY
BRIDGE 5101A CR 83 OVER REDWOOD RIVER**INSP. DATE: 11-02-2010****STRUCTURE UNIT: 0**

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
311	EXPANSION BEARING	2	11-02-2010	2 EA	0	0	2	N/A	N/A
			11-05-2009	2 EA	0	2	0	N/A	N/A
Notes: ROCKERS NEED ALIGNMENT 2007 rocker were realigned									
313	FIXED BEARING	1	11-02-2010	2 EA	0	2	0	N/A	N/A
			11-05-2009	2 EA	0	2	0	N/A	N/A
Notes: < none >									
215	CONCRETE ABUTMENT	2	11-02-2010	68 LF	68	0	0	0	N/A
			11-05-2009	46 LF	46	0	0	0	N/A
Notes: 2010 minor spalling and staining									
387	CONCRETE WINGWALL	2	11-02-2010	4 EA	4	0	0	0	N/A
			11-05-2009	4 EA	4	0	0	0	N/A
Notes: < none >									
357	PACK RUST	1	11-02-2010	1 EA	0	1	0	0	N/A
Notes: 2010 pack rust forming at lower chord gusset plate interface									
360	SETTLEMENT	1	11-02-2010	1 EA	1	0	0	N/A	N/A
Notes: possible settlement of both abutments									
361	SCOUR	2	11-02-2010	1 EA	1	0	0	N/A	N/A
			11-05-2009	1 EA	1	0	0	N/A	N/A
Notes: G - Foundation unknown. Evaluation and/or screening required.									
362	TRAFFIC IMPACT	1	11-02-2010	1 EA	0	1	0	N/A	N/A
Notes: 2010 flood debris damage at lower chord									
363	SECTION LOSS	1	11-02-2010	1 EA	0	1	0	0	N/A
Notes: 2010 section loss lower chord and lower gusset plates									
964	CRITICAL FINDING	2	11-02-2010	1 EA	1	0	N/A	N/A	N/A
			11-05-2009	1 EA	1	0	N/A	N/A	N/A
Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.									
966	FRACTURE CRITICAL	2	11-02-2010	1 EA	0	1	0	N/A	N/A
			11-05-2009	1 EA	1	0	0	N/A	N/A
Notes: 2010 flood debris damage of lower chord members. L0/L8 and U1/U7 required stiffening									
981	SIGNING	2	11-02-2010	1 EA	0	0	1	0	0
			11-05-2009	1 EA	1	0	0	0	0
Notes: 2010 posted at 22-40-40 tons									
985	SLOPES	2	11-02-2010	1 EA	1	0	0	N/A	N/A
			11-05-2009	1 EA	1	0	0	N/A	N/A
Notes: placed new slope protection 2001									

05/10/2011

Page 3 of 3

Mn/DOT BRIDGE INSPECTION REPORT

Inspected by: LYON COUNTY

BRIDGE 5101A CR 83 OVER REDWOOD RIVER

INSP. DATE: 11-02-2010

STRUCTURE UNIT: 0

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
967	GUSSET DISTORTION	1	11-02-2010	1 EA	0	1	0	0	N/A

Notes: 2010 detortion and pack rust at gusset plates

General Notes: Previous comments > smj & ckm
 2002smj
 2003 smj & ckm 2004 smj 2005 smj 2006 smj
 2007 smj MNDOT inspected the bridge found no major problems 2008smj 2009smj 2010smj

 Inspector's Signature

 Reviewer's Signature / Date

Appendix IV Laboratory Analysis Reports



EMSL Analytical, Inc.
14376 23rd Avenue North, Minneapolis, Mn 55447
Phone: (763) 449-8932 Fax: (763) 449-8934 Email: info@emslab.com

Attn: **Denise Cliff**
Institute For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445

Customer ID: IFEA50
Customer PO:
Received: 06/30/11 8:00 AM
EMSL Order: 351103777

Fax: (763) 315-7920 Phone: (763) 315-7900
Project: 1667-1112054, Lyon County Bridge #5101A, Ernest G. Fiala

EMSL Proj:

Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B*17000B)

Lab ID:	Analyzed	RDL	Lead Concentration	Notes
0001	6/30/2011	0.010 % wt	30 % wt	Site: Abut Girder near rocker Pin assembly-SW corner <i>Collected: 6/29/2011</i>
<i>Client Sample LP-1</i>				
0002	6/30/2011	0.010 % wt	17 % wt	Site: SE Corner @ Pin assembly <i>Collected: 6/29/2011</i>
<i>Client Sample LP-2</i>				
0003	6/30/2011	0.010 % wt	27 % wt	Site: Railing @ SW Corner <i>Collected: 6/29/2011</i>
<i>Client Sample LP-3</i>				
0004	6/30/2011	0.010 % wt	40 % wt	Site: Gusset Plate Assembly @ NE Corner <i>Collected: 6/29/2011</i>
<i>Client Sample LP-4</i>				
0005	6/30/2011	0.010 % wt	37 % wt	Site: Truss member @ NW Cor <i>Collected: 6/29/2011</i>
<i>Client Sample LP-5</i>				
0006	6/30/2011	0.010 % wt	29 % wt	Site: Truss member @ NE Cor <i>Collected: 6/29/2011</i>
<i>Client Sample LP-6</i>				

Initial report from 06/30/2011 14:58:58

Rachel Travis, Laboratory Manager
or other approved signatory

Reporting limit is 0.01 % wt. The QC data associated with these results included in this report meet the method QC requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. * slight modifications to methods applied.
Samples analyzed by EMSL Analytical, Inc, Minneapolis, Mn AHA-LAP, LLC ELLAP 163162

Appendix V
Chain of custody Documents

June 27, 2011

Denice Cliff
Institute for Environment Assessment, Inc.
9201 West Broadway, Suite 600
Brooklyn Park, MN 55445

Re: Testing for the presence of lead in paint; Samples LP-1 thru LP-6.
Lyon County Bridge # 5101A.

Dear Ms. Cliff:

Enclosed are six samples, LP-1 thru LP-6 which are to be tested for the presence of lead. All samples are in zip lock bags and labeled with sample numbers, dates of sampling, and project identification. Please forward the test results and required chain of custody forms to:

Ernest G. Fiala, PE
118 W. 3rd St.
Redwood Falls, MN 56283

ernie.fiala@gmail.com

507-637-2492
507-430-3600 Cell

Lyon County intends to demolish this structure as soon as possible and has requested a rush on the testing if at all possible. Please advise by E-mail above if this is possible. All fees incurred should be billed to the above. Should you have any questions or require additional information, please contact me at any of the above.

Sincerely,



Ernest G. Fiala, PE

Cc: File
Enclosures



CHAIN OF CUSTODY

2539

Page ___ of ___

37777

Client # 11607 Project # 1112054 Building Name Lyon County Bridge # 5101A Shaded Areas are for Laboratory Use Only!

Client Ernest G. Fiola Project Name Lead Sampling Contact Person Ernest G. Fiola Contact Person Phone _____

Address _____ Other Information _____

Verbal results to Dennis Phone, Fax No. or E-Mail _____

Verbal results relayed to _____ Verbal results relayed by EMSL

Analysis location: On Site Lab Regional Office Other

Sample #	Work Area or Phase #	Comments / Location	Sample type Material code	Volume	Matrix type			Analysis requested			Filter type				
					Air	Bulk	Dust	PCM	PLM	TEM	Other	MCB	8 um	4.5 um	
LP-1		About Girder near rocker pin assembly - SW corner			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LP-2		SE corner @ pin assembly			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LP-3		Railings @ SW corner			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LP-4		Gusset Plate Assembly @ NE corner			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LP-5		Truss member @ NW Cor			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LP-6		Truss member @ NE Cor			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

The MN Department of Health Alternative Indoor Air Standard for this project is:

Sampled by: <u>Client</u>	Date: _____	Time: _____	Delivered by: <u>Dennis</u>	Date: <u>6/29/11</u>	Time: _____
Received by: <u>Dennis</u>	Date: <u>6/29/11</u>	Time: _____	Delivered by: _____	Date: _____	Time: _____

F/C/C: _____ Batch Number: _____

Received by lab: SKY DB Date: 6/29/11 Time: 8:00AM

Analysis by: _____ Date: _____ Time: _____

Entered by: _____ Date: _____ Time: _____

Delivered by: _____ Date: _____ Time: _____

Samples Acceptable? Yes No

Appendix VI Laboratory Accreditations



AIHA Laboratory Accreditation Programs, LLC SCOPE OF ACCREDITATION

EMSL Analytical, Inc.
14375 23rd Avenue North, Minneapolis, MN 55447

Laboratory ID: 163162
Issue Date: 02/01/2011

The laboratory is approved for those specific field(s) of testing/methods listed in the table below. Clients are urged to verify the laboratory's current accreditation status for the particular field(s) of testing/Methods, since these can change due to proficiency status, suspension and/or revocation. A complete listing of currently accredited Environmental Lead laboratories is available on the AIHA-LAP, LLC website at: <http://www.aihaaccreditedlabs.org>

The EPA recognizes the AIHA-LAP, LLC ELLAP program as meeting the requirements of the National Lead Laboratory Accreditation Program (NLLAP) established under Title X of the Residential Lead-Based Paint Hazard Reduction Act of 1992 and includes paint, soil and dust wipe analysis. Air analysis is not included as part of the NLLAP.

Environmental Lead Laboratory Accreditation Program (ELLAP)

Initial Accreditation Date: 09/01/2010


Field of Testing (FoT)	Method	Method Description (for internal methods only)
Airborne Dust	NIOSH 7082	
	EPA SW-846 7000B	
Paint	EPA SW-846 3050B	
	EPA SW-846 7000B	
Settled Dust by Wipe	EPA SW-846 3050B	
	EPA SW-846 7000B	
Soil	EPA SW-846 7000B	
	EPA SW-846 3050B	

The laboratory participates in the following AIHA-LAP, LLC-approved proficiency testing programs:

- √ Paint
- √ Soil
- √ Settled Dust by Wipe
- √ Airborne Dust

Effective: 4/24/09
Scope ELLAP_R4
Page 1 of 1

Appendix VII
Inspector's Licensure and Certification



Appendix VIII



Minnesota Pollution Control Agency Notification of Intent to Perform a Bridge Demolition for Mn/DOT Operations.

Type of Notification: Original Amended Project Cancellation
 Notification must be postmarked or received ten (10) WORKING days before demolition begins.



Demolition Contractor:

Name: _____
 Address: _____

 City, State, Zip: _____
 Contact Person: _____
 Phone Number(s): _____

Bridge Information:

Bridge Name: _____
 Mile Point/Trunk Highway: _____
 Miles and direction (N.E.W.S) From Nearest Town: _____

 County: _____
 Project Engineer Phone Number(s): _____
 Age of Brdg. (years): _____ Size of Brdg. (sq. ft.): _____
 Type of Bridge: _____

Bridge Owner:

Name: _____
 Address: _____

 City, State, Zip: _____
 Contact person: _____
 Phone Number(s): _____

Suspect Materials to be checked for asbestos: pipes, asphalt underlay, spray-on and joint compounds.

Dates when demolition will Begin _____ & End _____

Both Beginning and Ending dates should be amended in writing as necessary to reflect current project dates.

There is no Asbestos Containing Material (ACM) present in the structure to be demolished

1. Company and/or individual that conducted the bridge inspection or record review, certification#, and the procedure used to determine the presence or absence of ACM (including analytic method): *Prior to demolition all bridges must be inspected by an MDH certified asbestos inspector.* _____

2. Description of planned demolition and the specific method(s) that will be used: _____

Demolition Material will be recycled on site or a metal scrap recycler, Material not recycled will be sent to:

3. Demolition Waste Transporter(s) Information:

Transporter Name: _____
 Transporter Contact: _____
 Transporter Address: _____
 City, State, Zip: _____
 Phone Number: _____

4. Demolition Waste Disposal Information:

Landfill Name: _____
 Owner/Operator: _____
 Address/Location: _____
 City, State, Zip: _____
 Phone Number: _____

5. I certify that the above information is correct and I am a bonafide representative of the demolition contractor or bridge owner and have authority to enter into agreements for my employer. In event that unexpected asbestos containing material is found, the material will be removed by a MDH certified asbestos abatement contractor.

Signature of Contractor, Owner Agent _____

Date _____

Send to: Minnesota Pollution Control Agency Regional Environmental Management Division 520 Lafayette Road North St. Paul, MN 55155-4194	For questions call: 651-296-6300 1-800-657-3864 FAX: 651-215-1593
--	--

PCB Removal Information *Polychlorinated Biphenyls (PCBs) will be removed from the bridge prior to demolition.*

Mercury Removal Information *Material containing mercury will be removed from the bridge prior to demolition.*

[Notification of Intent to Perform a Demolition form (1)

Revised 08 04

CC: Mark Vogel, OES, MS 620

Appendix IX
Notification Form on Transfer of Bridge Steel

NOTIFICATION FORM ON DISPOSAL OF BRIDGE STEEL

The Contractor is required to provide certain information on disposal of bridge steel which has been painted with lead-based paint. By signing this document, the Contractor certifies that information supplied by the Contractor is correct and that the Contractor is familiar with proper handling and disposal of materials with lead-based paint. This information must be furnished to the Project Engineer a minimum of 30 days prior to removal of the bridge steel from the project site. Any change in method or location of disposal would require resubmittal and a 30 day notice.

Mn/DOT Project No. _____ Bridge No. _____

Description of Bridge Steel _____

Paint System is Mn/DOT Spec. _____
(Primer) (Top Coat)

Project Engineer: _____

Contractor/Subcontractor: _____
(Name, mailing address, telephone no.)

I _____ certify that the following information is correct:
(print name of authorized representative)

The above bridge steel will be disposed of by the following method(s): _____
(list name,

address and telephone no. of recipient, estimated delivery date, and intended use.)

I also certify that _____ is familiar with
(Contractor/Subcontractor name)
the requirements in OSHA 29 CFR 1926.62 relating to lead, precautions to be taken when working with lead, and proper handling and disposal of materials with lead-based paint systems and that _____ has been notified of the presence of lead-based paint.
(name of recipient)

(signature) (date)

Received by Project Engineer/Inspector: _____
(date) (signature)

cc: Project File
Office of Environmental Services

Appendix X
Notification Form on Ownership Transfer
of Treated Wood

1 of 2 pages

NOTIFICATION FORM ON OWNERSHIP TRANSFER OF TREATED WOOD

The prospective buyer identified below has expressed interest in obtaining treated wood from Mn/DOT for reuse/recycling. Treated wood can include, but is not limited to: copper chromium arsenic (CCA), ammoniacal copper quat (ACQ), copper azole, ammoniacal copper citrate, creosote, and pentachlorophenol (PCP or penta). By signing this document, the buyer certifies that he or she is familiar with proper handling and disposal of this material. The buyer must complete this form to Mn/DOT's satisfaction prior to removal of any treated wood. Any change in the method or location of re-use of the materials would require re-submittal and approval.

Source of treated wood: _____

Mn/DOT Contract: _____

Buyer: _____
(name, company, mailing address, telephone number)

I _____ certify that the following information is correct:
(Print name of authorized buyer)

The above treated wood will be reused in the following manner: _____

I also certify that _____ is familiar with Local, State and
(buyer name)

Federal requirements, including the Minnesota Pollution Control Agency fact sheet "Treated Wood: Use, Disposal and Alternatives for Businesses", regarding proper handling and disposal of treated wood and the buyer has been notified of this.

(buyers signature) (date)

Received by Mn/DOT representative: _____
(print name)

(signature) (date)

cc: District File
Office of Environmental Services (Mail stop 620)

