


**ASBESTOS & REGULATED WASTE
ASSESSMENT REPORT**

**BRIDGE# R0122
LYND TOWNSHIP
LYON COUNTY, MN**



Prepared for:

**Lyon County Highway Department
Suhail Kanwar, P.E., County Engineer**

September 22, 2011

TABLE OF CONTENTS

	Page
Site Specifics & Certifications	3
Summary of all Asbestos & Regulated Waste & Actions Required for this Demolition	4
2.1 Asbestos Summary	4
2.2 Lead Summary	4
2.3 Regulated Waste Summary	4
Appendix I Sample location Photographs	5-6
Appendix II Site Location Photographs	7-11
Appendix III MN/DOT Structure Inventory Report	12-14
Appendix IV Laboratory Analysis Report	15
Appendix V Chain of Custody Documents	16-17
Appendix VI Laboratory Accreditations	18-19
Appendix VII Inspectors Licensure and Certification	20
Appendix VIII MPCA Notification of Intent to Perform a Bridge Demolition for MN/DOT Operations Form	21
Appendix IX Notification Form on Transfer of Bridge Steel	22
Appendix X Notification Form on Ownership Transfer of Treated Wood	23-24

Site Specifics & Certifications

Bridge No.: R0122

Location: On CR 83 over Redwood River, 0.8 Mi. Southwest of Lynd in Lynd Township, Lyon County, Minnesota; Sec 32, T111N, R42W.

Type of Structure: Bridge # R0122 is a 50.3' x 15.8', single span, steel Warren low truss bridge built in 1925.

Railing: Steel angle iron affixed to truss members.

Decking: Timber.

Superstructure: Timber deck on steel stringers with bituminous wearing surface and nomembrane present per MN/DOT Structure Inventory Report dated 05/10/2011, and site inspection 06/15/2011.

Substructure: C-I-P concrete abutments on footing pile. See MN/DOT Structure Inventory Report dated 05/10/2011 and Site Photographs Appendix II.


Current Owner: Lyon County.

Disposition of Structure: Demolition

Licensure: MDH Certified Asbestos Inspector, Ernest G. Fiala, P.E. Conducted this Inspection (See Appendix IV).

Certification: The undersigned certifies that this asbestos inspection was performed on June 15, 2011, in compliance with MN Rules 4620.3460.

This report was compiled under my direct supervision. I have reviewed the report's contents and find it to meet MN/DOT requirements as described in the "Asbestos & Regulated Waste Manual for Structure Demolition or Relocations for Construction Projects."



**Ernest G. Fiala, P.E. Reg. No. 18480
MDH Asbestos Inspector #AI10135**

Summary of all Asbestos & Regulated Waste & Actions Required for this Demolition

Based on a field inspection, the following conclusions are summarized for Asbestos & Regulated Waste Assessment. Applicable items listed below should be removed and/or stabilized prior to demolition of Bridge # R0122.

2.1 Asbestos Summary

No asbestos or asbestos containing materials were found on structure.

2.2 Lead Summary

Sample LP-1 was taken from the truss member at lower chord gusset plate. NE corner of bridge and indicated a lead concentration of 8.3%.

Sample LP-2 was taken from the bridge rail on upstream side, North end of bridge and indicated a lead concentration of 0.070%.

Sample LP-3 was taken from the truss member at the lower chord gusset plate, SW corner of bridge and indicated a lead concentration of 0.049%.

Sample LP-4 was taken from the downstream fascia beam at the South end of bridge and indicated a lead concentration of 0.33%.

Pictures of all sample locations are included in Appendix I.

2.3 Regulated Waste Summary

The following Regulated Waste was observed on or in the vicinity of the bridge.

2.3.1 Mercury – None

2.3.2 PCBs – None

2.3.3 CFCs – None

2.3.4 Treated wood –None

2.3.5 Household Hazardous Waste - None.


2.3.6 White Goods - None.

2.3.7 Solid Waste - None.

2.3.8 There is a possible utility in a conduit on the upstream side of bridge. Type and owner unknown. Conduit appears to be steel pipe.

2.3.9 There is a stand pipe on the West R/W line approximately 100' North of the bridge. Function and owner unknown.


Appendix I
Sample Location Photographs




**Sample LP-1. Lead paint sample from truss member at lower chord gusset plate.
NE corner of bridge.**



Sample LP-2. Lead paint sample from bridge rail on upstream side, North end of bridge.



**Sample LP-3. Lead paint sample from truss member at lower chord gusset plate.
SW corner of bridge.**



Sample LP-4. Lead paint sample from downstream fascia beam at South end of structure.

Appendix II
Site Location Photographs



South approach to bridge looking North.



North approach to bridge looking South.



West side of bridge.



East side of bridge.



C-I-P concrete abutment at South end of bridge.



Under side of deck showing timber deck on steel stringers.



Possible utilities in conduit on upstream side of bridge. Owner unknown.



Conduit on upstream side of bridge.



**Stand pipe installation on West R/W line approximately 100' North of bridge.
Owner and function unknown.**

Appendix III

MN/DOT Structure Inventory and

Bridge Inspection Reports

Mn/DOT Structure Inventory Report

Bridge ID: R0122 CR 83 over REDWOOD RIVER

Date: 05/10/2011

+ GENERAL +	+ ROADWAY +	+ INSPECTION +
Agency Br. No. S1	Bridge Match ID (TIS) 1	Deficient Status ADEQ
District 8 Maint. Area	Roadway O/U Key 1-ON	Sufficiency Rating 55.6
County 42 - LYON	Route Sys/Nbr CNTY 83	Last Inspection Date 11-02-2010
City	Roadway Name or Description	Inspection Frequency 12
Township LYND	CR 83	Inspector Name LYON
Desc. Loc. 0.8 MI SW OF LYND	Roadway Function MAINLINE	Structure P-LOAD POSTED
Sect., Twp., Range 32 - 111N - 42W	Roadway Type 1 LN;2 WAY	+ NB I CONDITI ON RATINGS +
Latitude 44d 22m 19.80s	Control Section (TH Only)	Deck 8
Longitude 95d 55m 22.18s	Ref. Point (TH Only)	Superstructure 6
Custodian COUNTY	Date Opened to Traffic	Substructure 8
Owner COUNTY	Detour Length 2 mi.	Channel 8
Inspection By LYON COUNTY	Lanes 1 Lane ON Bridge	Culvert N
BMU Agreement	ADT (YEAR) 40 (2005)	+ NB I APPRAISAL RATINGS +
Year Built 1925	HCA DT	Structure Evaluation 4
Year Fed Rehab	Functional Class. RURAL LOCAL	Deck Geometry 8
Year Remodeled 1986	+ RDWY DIMENSIONS +	Underclearances N
Temp	If Divided NB-EB SB-WB	Waterway Adequacy 8
Plan Avail. NO PLAN	Roadway Width 15.8 ft	Approach Alignment 8
+ STRUCTURE +	Vertical Clearance	+ SAFETY FEATURES +
Service On HIGHWAY	Max. Vert. Clear.	Bridge Railing 0-SUBSTANDARD
Service Under STREAM	Horizontal Clear.	GR Transition N-NOT REQUIRED
Main Span Type STEEL LOW TRUSS	Lateral Cir. - Lt/Rt	Appr. Guardrail N-NOT REQUIRED
Main Span Detail WARREN W/VERT	Appr. Surface Width 28.0 ft	GR Termini N-NOT REQUIRED
Appr. Span Type	Roadway Width 15.8 ft	+ IN DEPTH INSP. +
Appr. Span Detail	Median Width	Frac. Critical Y 24 mo 09/2010
Skew	+ MI SC. BRIDGE DATA +	Underwater
Culvert Type	Structure Flared NO	Pinned Asbly.
Barrel Length	Parallel Structure NONE	Spec. Feat.
Number of Spans	Field Conn. ID RIVETED	+ WATERWAY +
MAIN: 1 APPR: 0 TOTAL: 1	Cantilever ID	Drainage Area
Main Span Length 47.5 ft	Foundations	Waterway Opening 500 sq ft
Structure Length 50.3 ft	Abut. CONC - FTG PILE	Navigation Control NO PRMT REQD
Deck Width 15.8 ft	Pier N/A	Pier Protection NOT APPL
Deck Material TIMBER	Historic Status NOT ELIGIBLE	Nav. Vert./Horz. Cir.
Wear Surf Type BITUMINOUS	On - Off System OFF	Nav. Vert. Lift Bridge Clear.
Wear Surf Install Year	+ PAINT +	MN Scour Code G-FND UNKN;EVAL
Wear Course/Fill Depth 0.08 ft	Year Painted 1986 Pct. Unsound 5 %	Scour Evaluation Year
Deck Membrane NONE	Painted Area	+ CAPACITY RATINGS +
Deck Protect. N/A	Primer Type LEAD, IRON OXIDE	Design Load UNKN
Deck Install Year	Finish Type VINYL	Operating Rating HS 15.40
Structure Area 795 sq ft	+ BRIDGE SIGNS +	Inventory Rating HS 9.20
Roadway Area 797 sq ft	Posted Load VEHICLE & SEMI	Posting VEH: 24 SEMI: 40 DBL: 40
Sidewalk Width - L/R	Traffic NOT REQUIRED	Rating Date 01-11-2008
Curb Height - L/R	Horizontal OBJECT MARKERS	Mn/DOT Permit Codes
Rail Codes - L/R 02 02	Vertical NOT APPLICABLE	A: N B: N C: N

05/10/2011

Page 1 of 2

Mn/DOT BRIDGE INSPECTION REPORT

Inspected by: LYON COUNTY

BRIDGE R0122 CR 83 OVER REDWOOD RIVER

INSP. DATE: 11-02-2010

County: LYON	Location: 0.8 MI SW OF LYND	Length: 50.3 ft
City:	Route: CNTY 83 Ref. Pt.: 000+00.910	Deck Width: 15.8 ft
Township: LYND	Control Section: Maint. Area:	Rdwy. Area / Pct. Unsnd: 797 sq ft
Section: 32 Township: 111N Range: 42W	Local Agency Bridge Nbr: S1	Paint Area/ Pct. Unsnd: 5 %
Span Type: STEEL LOW TRUSS		Culvert N/A
NBI Deck: 8 Super: 6 Sub: 8 Chan: 8 Culv: N	Open, Posted, Closed: LOAD POSTED	Postings: 24 - 40 - 40
Appraisal Ratings - Approach: 8 Waterway: 8	MN Scour Code: G-FND UNKN;EVAL	Def. Stat: ADEQ Suff. Rate: 55.6
Required Bridge Signs - Load Posting: VEHICLE & SEMI	Traffic: NOT REQUIRED	
Horizontal: OBJECT MARKERS	Vertical: NOT APPLICABLE	

STRUCTURE UNIT: 0

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
32	TIMBER DECK-BIT O/L	1	11-02-2010	797 SF	797	0	0	0	N/A
Notes:									
407	BITUMINOUS APPROACH	1	11-02-2010	2 EA	0	2	0	0	N/A
Notes: 2010 2" settlement east side and 3" settlement west side									
334	METAL RAIL-COATED	2	11-02-2010 11-05-2009	98 LF 98 LF	0 98	92 0	6 0	0 0	0 0
Notes: 2010 minor rust = condition 2 The NW and NE corners have impact damage = condition 3									
113	PAINT STEEL STRINGER	1	11-02-2010 11-05-2009	299 LF 299 LF	0 0	0 0	299 299	0 0	0 0
Notes: 2010 Bottom flange of stringers have extensive corrosion									
121	P/STL THRU TRUSS/BOT	1	11-02-2010 11-05-2009	98 LF 98 LF	0 0	0 98	88 0	10 0	0 0
Notes: 2002 scattered rust Impact damage has caused the bottom chord to be bent upward 3" from L6-L8 north. At panel L4 north 2 rivets are broken and the batten plate is bent down									
126	P/STL THRU TRUSS/TOP	1	11-02-2010 11-05-2009	98 LF 98 LF	0 0	98 98	0 0	0 0	0 0
Notes: 2010 minor corrosion									
152	PAINT STL FLOORBEAM	1	11-02-2010 11-05-2009	52 LF 52 LF	0 0	0 52	52 0	0 0	0 0
Notes: 2010 bottom of flanges have corrosion									
423	GUSSET PLATE (PAINT)	1	11-02-2010	18 EA	0	18	0	0	0
Notes: 2010 Minor surface erosion									
380	SECONDARY ELEMENTS	1	11-02-2010	1 EA	0	1	0	0	N/A
Notes: 2010 Cross bracing in bays 2 3 are bent									
310	ELASTOMERIC BEARING	2	11-02-2010 11-05-2009	4 EA 4 EA	4 4	0 0	0 0	N/A N/A	N/A N/A
Notes: < none >									
215	CONCRETE ABUTMENT	2	11-02-2010 11-05-2009	33 LF 33 LF	33 33	0 0	0 0	0 0	N/A N/A
Notes: < none >									

05/10/2011

Mn/DOT BRIDGE INSPECTION REPORT

Page 2 of 2

Inspected by: LYON COUNTY

BRIDGE R0122 CR 83 OVER REDWOOD RIVER

INSP. DATE: 11-02-2010

STRUCTURE UNIT: 0

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
387	CONCRETE WINGWALL		2 11-02-2010	4 EA	4	0	0	0	N/A
			11-05-2009	4 EA	4	0	0	0	N/A
Notes: < none >									
357	PACK RUST		1 11-02-2010	1 EA	0	1	0	0	N/A
Notes: 2010 Minor scalloping of top cord due to pack rust									
361	SCOUR		2 11-02-2010	1 EA	1	0	0	N/A	N/A
			11-05-2009	1 EA	1	0	0	N/A	N/A
Notes: G - Foundation unknown. Evaluation and/or screening required.									
362	TRAFFIC IMPACT		1 11-02-2010	1 EA	0	1	0	N/A	N/A
Notes: 2010 impact damage has occurred lower chord truss (north)									
964	CRITICAL FINDING		2 11-02-2010	1 EA	1	0	N/A	N/A	N/A
			11-05-2009	1 EA	1	0	N/A	N/A	N/A
Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.									
966	FRACTURE CRITICAL		2 11-02-2010	1 EA	0	1	0	N/A	N/A
			11-05-2009	1 EA	1	0	0	N/A	N/A
Notes: Do Not Remove. See in-depth report for location of F/C members. 2010 lower chord has impact damage									
981	SIGNING		1 11-02-2010	1 EA	0	0	1	0	0
			11-05-2009	1 EA	0	0	1	0	0
Notes: NEEDS END MARKERS									
985	SLOPES		2 11-02-2010	1 EA	1	0	0	N/A	N/A
			11-05-2009	1 EA	1	0	0	N/A	N/A
Notes: NEW SLOPE PROTECTION 2001									
967	GUSSET DISTORTION		1 11-02-2010	1 EA	0	1	0	0	N/A
Notes: 2010 plate distortion of up to 1/8" due to pack rust									

General Notes: 1993 - Bridge washed down river in 93 flood - no bridge at this location. 1994 - REPLACED WITH NEW BRIDGE
 1997 needs endmarkers
 SMJ
 2002smj 2003 smj & ckm 2005 smj 2007smj 2008smj 2009smj

Inspector's Signature

Reviewer's Signature / Date

Appendix IV
Laboratory Analysis Reports



EMSL Analytical, Inc.
14375 23rd Avenue North, Minneapolis, Mn 55447
Phone: (651) 416-1693 Fax: (763) 448-4924 Email: mn@emsl.com

Attn: **Denice Cliff**
Institute For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445

Customer ID: IFEA50
Customer PO:
Received: 09/29/11 11:20 AM
EMSL Order: 351103755

Fax: (763) 315-7920 Phone: (763) 315-7900
Project: 1667-1112052, Lyon County Bridge #R0122, Ernest Fiela

EMSL Proj:

Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B*/7000B)

Lab ID:	Analyzed	RDL	Lead Concentration	Notes
0001	6/29/2011	0.010 % wt	8.3 % wt	Site: Truss mem @ lower chrod Gusset, NE Cor <i>Collected: 6/28/2011</i>
<i>Client Sample LP-1</i>				
0002	6/29/2011	0.010 % wt	0.070 % wt	Site: Rail on upstream side N. end <i>Collected: 6/28/2011</i>
<i>Client Sample LP-2</i>				
0003	6/29/2011	0.016 % wt	0.049 % wt	Site: Truss mem. @ lower chrod Gusset SW Corner <i>Collected: 6/28/2011</i>
<i>Client Sample LP-3</i>				
0004	6/29/2011	0.077 % wt	0.33 % wt	Site: Downstream fascia beam S. end <i>Collected: 6/28/2011</i>
<i>Client Sample LP-4</i>				

Initial report from 09/29/2011 16:28:25

Rachel Travis, Laboratory Manager
or other approved signatory

Reporting limit is 0.01 % wt. The QC data associated with these results included in this report meet the method QC requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. * slight modifications to methods applied.
Samples analyzed by EMSL Analytical, Inc. Minneapolis, Mn AHA-LAP, LLC ELLAP 163162

Appendix V
Chain of custody Documents

June 27, 2011

Denice Cliff
Institute for Environment Assessment, Inc.
9201 West Broadway, Suite 600
Brooklyn Park, MN 55445

Re: Testing for the presence of lead in paint; Samples LP-1 thru LP-4.
Lyon County Bridge # R0122.

Dear Ms. Cliff:

Enclosed are four samples, LP-1 thru LP-4 which are to be tested for the presence of lead. All samples are in zip lock bags and labeled with sample numbers, dates of sampling, and project identification. Please forward the test results and required chain of custody forms to:


Ernest G. Fiala, PE
118 W. 3rd St.
Redwood Falls, MN 56283

ernie.fiala@gmail.com

507-637-2492
507-430-3600 Cell

Lyon County intends to demolish this structure as soon as possible and has requested a rush on the testing if at all possible. Please advise by E-mail above if this is possible. All fees incurred should be billed to the above. Should you have any questions or require additional information, please contact me at any of the above.

Sincerely,


Ernest G. Fiala, PE

Cc: File
Enclosures


CHAIN OF CUSTODY 2532
 Page 3755 of

9201 West Broadway North, Suite 600
 Brooklyn Park, MN 55445
 (763) 315-7900
 1-800-233-9513

Client #	11017	Project #	112052	Building Name	Lyon County Bridge # R0122	Shaded Areas are for Laboratory Use Only!	
Client	Ernst Fiala	Project Name	Lead Samples	Contact Person			
Address						Contact Person Phone	
Other Information							
Verbal results to	Denise					Phone, Fax No. or E-Mail	
Verbal results relayed to						TAT (circle) 6 hr 1d 2d 3d 4d Specify	
Analysis location: <input type="radio"/> On Site <input type="radio"/> Lab <input type="radio"/> Regional Office <input checked="" type="radio"/> Other <u>EMSL</u>							
Sample #	Work Area or Phase #	Comments / Location	Sample type or Material code	Volume	Matrix type	Analysis requested	Filter type
LP-1		Truss mem @ lower chord Gusset, NE Cor.			Air	PCM	0.45 um
LP-2		Rail on upstream side N. end			Bulk	TEM	0.8 um
LP-3		Truss mem @ lower chord Gusset S. D. Corner				Other	MCF
LP-4		Downdraft fabric beam S. end					
The MN Department of Health Alternative Indoor Air Standard for this project is:							
Sampled by	Client	Delivered by	Denise Hill	F/CC	Batch Number:	Received by lab	Analysis by
Received by	Denise Hill	Delivered by	Denise Hill	Time	Time	Time	Time
Date	11/20	Date	11/20	Date	10/29	Date	11/20
Time	11:20	Time	11:20	Time	11:20	Time	11:20
Samples Acceptable? <input type="radio"/> Yes <input type="radio"/> No							
Entered by							
Delivered by							

Appendix VI

Laboratory Accreditations



AIHA Laboratory Accreditation Programs, LLC

SCOPE OF ACCREDITATION

EMSL Analytical, Inc.
14375 23rd Avenue North, Minneapolis, MN 55447

Laboratory ID: 163162
Issue Date: 02/01/2011

The laboratory is approved for those specific field(s) of testing/methods listed in the table below. Clients are urged to verify the laboratory's current accreditation status for the particular field(s) of testing/Methods, since these can change due to proficiency status, suspension and/or revocation. A complete listing of currently accredited Environmental Lead laboratories is available on the AIHA-LAP, LLC website at: <http://www.aihaaccreditedlabs.org>

The EPA recognizes the AIHA-LAP, LLC ELLAP program as meeting the requirements of the National Lead Laboratory Accreditation Program (NLLAP) established under Title X of the Residential Lead-Based Paint Hazard Reduction Act of 1992 and includes paint, soil and dust wipe analysis. Air analysis is not included as part of the NLLAP.

Environmental Lead Laboratory Accreditation Program (ELLAP)

Initial Accreditation Date: 09/01/2010

Field of Testing (FoT)	Method	Method Description <i>(for internal methods only)</i>
Airborne Dust	NIOSH 7082	
Paint	EPA SW-846 7000B	
	EPA SW-846 3050B	
Settled Dust by Wipe	EPA SW-846 7000B	
	EPA SW-846 3050B	
Soil	EPA SW-846 7000B	
	EPA SW-846 3050B	

The laboratory participates in the following AIHA-LAP, LLC-approved proficiency testing programs:

- ✓ Paint
- ✓ Soil
- ✓ Settled Dust by Wipe
- ✓ Airborne Dust

Effective: 4/24/09
Scope_ELLAP_R4
Page 1 of 1



AIHA
Laboratory Accreditation
Programs, LLC

AIHA Laboratory Accreditation Programs, LLC

acknowledges that

EMSL Analytical, Inc.
14375 23rd Avenue North, Minneapolis, MN 55447
Laboratory ID: 163162

along with all premises from which key activities are performed, as listed above, has fulfilled the requirements of the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC accreditation to the ISO/IEC 17025:2005 international standard, *General Requirements for the Competence of Testing and Calibration Laboratories* in the following:

LABORATORY ACCREDITATION PROGRAMS

- INDUSTRIAL HYGIENE Accreditation Expires: 03/01/2013
- ENVIRONMENTAL LEAD Accreditation Expires: 03/01/2013
- ENVIRONMENTAL MICROBIOLOGY Accreditation Expires: 03/01/2013
- FOOD

Specific Field(s) of Testing (FoT)/Method(s) within each Accreditation Program for which the above named laboratory maintains accreditation is outlined on the attached Scope of Accreditation. Continued accreditation is contingent upon successful on-going compliance with ISO/IEC 17025:2005 and AIHA-LAP, LLC requirements. This certificate is not valid without the attached Scope of Accreditation. Please review the AIHA-LAP, LLC website (www.aihaaccreditedlabs.org) for the most current Scope.


Christine Powell

Christine Powell
Chairperson, Analytical Accreditation Board
Revision 10-01/13/2011

Cheryl O. Morton

Cheryl O. Morton
Director, AIHA Laboratory Accreditation Programs, LLC
Date Issued: 02/01/2011

Appendix VII
Inspector's Licensure and Certification



Appendix VIII



Minnesota Pollution Control Agency Notification of Intent to Perform a Bridge Demolition for Mn/DOT Operations.

Type of Notification: Original Amended Project Cancellation
Notification must be postmarked or received ten (10) WORKING days before demolition begins.



Demolition Contractor:

Name: _____
Address: _____
City, State, Zip: _____
Contact Person: _____
Phone Number(s): _____

Bridge Information:

Bridge Name: _____
Mile Point/Trunk Highway: _____
Miles and direction (N,E,W,S) From Nearest Town: _____
County: _____
Project Engineer Phone Number(s): _____
Age of Brdg. (years): _____ Size of Brdg. (sq. ft.): _____
Type of Bridge: _____

Bridge Owner:

Name: _____
Address: _____
City, State, Zip: _____
Contact person: _____
Phone Number(s): _____

Suspect Materials to be checked for asbestos: pipes, asphalt underlay, spray-on and joint compounds.
Dates when demolition will Begin _____ & End _____
Both Beginning and Ending dates should be amended in writing as necessary to reflect current project dates.

There is no Asbestos Containing Material (ACM) present in the structure to be demolished

1. Company and/or individual that conducted the bridge inspection or record review, certification#, and the procedure used to determine the presence or absence of ACM (including analytic method): *Prior to demolition all bridges must be inspected by an MDH certified asbestos inspector.* _____

2. Description of planned demolition and the specific method(s) that will be used: _____

Demolition Material will be recycled on site or a metal scrap recycler, Material not recycled will be sent to:

3. Demolition Waste Transporter(s) Information:
Transporter Name: _____
Transporter Contact: _____
Transporter Address: _____
City, State, Zip: _____
Phone Number: _____

4. Demolition Waste Disposal Information:
Landfill Name: _____
Owner/Operator: _____
Address/Location: _____
City, State, Zip: _____
Phone Number: _____

5. I certify that the above information is correct and I am a bonafide representative of the demolition contractor or bridge owner and have authority to enter into agreements for my employer. In event that unexpected asbestos containing material is found, the material will be removed by a MDH certified asbestos abatement contractor.

Signature of Contractor, Owner Agent _____

Date _____

Send to: Minnesota Pollution Control Agency
Regional Environmental Management Division
520 Lafayette Road North
St. Paul, MN 55155-4194

For questions call:
651-296-6300
1-800-657-3864
FAX: 651-215-1593

PCB Removal Information Polychlorinated Biphenyls (PCBs) will be removed from the bridge prior to demolition.

Mercury Removal Information Material containing mercury will be removed from the bridge prior to demolition.

[Notification of Intent to Perform a Demolition form 1]

Revised 08/04

CC: Mark Vogel, OES, MS 620

Appendix IX
Notification Form on Transfer of Bridge Steel

NOTIFICATION FORM ON DISPOSAL OF BRIDGE STEEL

The Contractor is required to provide certain information on disposal of bridge steel which has been painted with lead-based paint. By signing this document, the Contractor certifies that information supplied by the Contractor is correct and that the Contractor is familiar with proper handling and disposal of materials with lead-based paint. This information must be furnished to the Project Engineer a minimum of 30 days prior to removal of the bridge steel from the project site. Any change in method or location of disposal would require resubmittal and a 30 day notice.

Mn/DOT Project No. _____ Bridge No. _____

Description of Bridge Steel _____

Paint System is Mn/DOT Spec. _____
(Primer) (Top Coat)

Project Engineer: _____

Contractor/Subcontractor: _____
(Name, mailing address, telephone no.)

I _____ certify that the following information is correct:
(print name of authorized representative)

The above bridge steel will be disposed of by the following method(s): _____
(list name, address and telephone no. of recipient, estimated delivery date, and intended use.)

I also certify that _____ is familiar with
(Contractor/Subcontractor name)
the requirements in OSHA 29 CFR 1926.62 relating to lead, precautions to be taken when working with lead, and proper handling and disposal of materials with lead-based paint systems and that _____ has been notified of the presence of lead-based paint.
(name of recipient)

(signature) (date)

Received by Project Engineer/Inspector: _____
(date) (signature)

cc: Project File
Office of Environmental Services

Appendix X
Notification Form on Ownership Transfer
of Treated Wood

1 of 2 pages

NOTIFICATION FORM ON OWNERSHIP TRANSFER OF TREATED WOOD

The prospective buyer identified below has expressed interest in obtaining treated wood from Mn/DOT for reuse/recycling. Treated wood can include, but is not limited to: copper chromium arsenic (CCA), ammoniacal copper quat (ACQ), copper azole, ammoniacal copper citrate, creosote, and pentachlorophenol (PCP or penta). By signing this document, the buyer certifies that he or she is familiar with proper handling and disposal of this material. The buyer must complete this form to Mn/DOT's satisfaction prior to removal of any treated wood. Any change in the method or location of re-use of the materials would require re-submittal and approval.

Source of treated wood: _____

Mn/DOT Contract: _____

Buyer: _____
(name, company, mailing address, telephone number)

I _____ certify that the following information is correct:
(Print name of authorized buyer)

The above treated wood will be reused in the following manner: _____

I also certify that _____ is familiar with Local, State and
(buyer name)

Federal requirements, including the Minnesota Pollution Control Agency fact sheet "Treated Wood: Use, Disposal and Alternatives for Businesses", regarding proper handling and disposal of treated wood and the buyer has been notified of this.

(buyers signature) (date)

Received by Mn/DOT representative: _____
(print name)

(signature) (date)

cc: District File
Office of Environmental Services (Mail stop 620)

